




PWB 508631 REV C  
5-31-06  
BOTTOM SIDE - LAYER 12






PWB 508631 REV C  
5-31-06  
BOTTOM SIDE SOLDERMASK




PWB 508631 REV C  
5-31-06  
GND PLANE - LAYER 2,5,8 & 11



3


PWB 508631 REV C  
5-31-06  
MID LAYER 1 - LAYER 3




4

PWB 508631 REV C  
5-31-06  
MID LAYER 2 - LAYER 4






PWB 508631 REV C  
5-31-06  
MID LAYER 3 - LAYER 9




10


PWB 508631 REV C  
5-31-06  
MID LAYER 4 - LAYER 10




PWB 508631 REV C  
5-31-06  
TOP SIDE - LAYER 1




PWB 508631-0001 REV C  
5-31-06  
TOP SIDE SILKSCREEN






PWB 508631 REV C  
5-31-06  
TOP SIDE SOLDERMASK



PWB 508631 REV C  
5-31-06  
VCC PLANE 2 - LAYER 7



PWB 508631 REV C  
5-31-06  
VCC PLANE - LAYER 6



